ELECON® NEVS



Major Dry Cleaning Plant in Moscow Repairs & Protects Floors with DuraQuartz, ENECLAD CFS & CHEMCLAD SC









Client: Dry Cleaning Plant

Location: Moscow, Russia

Problem: Concrete floor was severely cracked and pitted. Previous coatings had failed.

Solution: Remove loose concrete and previous coatings by mechanical grinding.
Repair cracks and joints with ENECRETE DuraQuartz. Prime entire floor with ENECLAD CFS. Provide corrosion and chemical resistance with CHEMCLAD SC.

The dry cleaning plant management was extremely happy with the final results.

